



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 18, 2009

Reviewed RBZ

Mine Name: Dugway Pass	Permit Number: S/023/0091
Operator Name: Davies, Wingle & Davies, Inc.	Inspection Date: May 14, 2009
Inspector(s): Wayne Western & Brett Gregory	Time: 5:00 pm
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: None listed **Bond Amount:** \$18,750

Purpose of Inspection: This was a routine annual inspection.

Inspection Summary: No additional ground disturbance was noted on the site since the last inspection (10-24-2007). The site was visited and the disturbance was limited to the access road and a trench. The actual trench area needs some site clean up as junk (i.e. lights, pipe, litter) was scattered about. There is also a grizzly screen documented below that needs to be removed.

Conclusions and Recommendations: Continue to monitor this site when in the area. The operator needs to maintain a cleaner site when not mining as well as saving topsoil from disturbed areas for reclamation.

Inspector's Signature

WHW, BG:pb

cc: Roger Davies

Will Stokes – SITLA

Attach - GIS

O:\M023-Juab\S0230091-Dugwaypass\inspections\Insp_DugwayPass_05-14-08.doc



Ground disturbance.



Garbage to be removed.



Mine Number: S230091
Mine Name: DUGWAY PASS
 Township 11.0 S Range 11.0 W Section 16 SLBM

Inspection Date: 10/25/2007
 Map Produced by DKS

Acres Disturbed	0,13
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0,57

Total Acres Disturbed 0,7

Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend
 All items symbolized in legend may not be appear on map.



NAIP Imagery date 2006



0 625

feet
 1:7,500 1 inch equals 625 feet
 Verify Scale

Dept. of Natural Resources
 Division of Oil, Gas, and Mining
 Mineral Mines Program

Different data sources and input scales
 may cause misalignment of data layers.
 This product may not meet DORM
 standards for accuracy and content.